Spiral cable management

Spiral shown extended for illustration purposes.

Contents

|		Ø3.5X30
x1	x1	x1

Installing the fixing brackets

Attach the top hat to the underside of the desk with the supplied fixing screw.

Ensure the top hat is secured firmly in place but do not overtighten the screw.

Installing the cables

With the cable spine in the collapsed state, feed the cables through the top aperture as shown.

Guide the cables out of the base and through the recess to allow the base to sit flat.

Installing the cable spine (top)

Guide the slot on top of the cable spine onto the top hat fixing under the desk.

'SNAP'

Push the top of the cable spine towards the top hat until it snaps into place.

Cable spine adjustment

165mm

1300mm

The cable spine can be used up to a maximum height of 1300mm. The collapsed height of the cable spine is 165mm.

Additional information

Safety

- Installation is to be carried out in accordance with relevant Health & Safety regulations and only to be carried out by a skilled or competent person.
- The product should be installed to comply with the relevant national standards and be inspected and tested prior to being put into service (in the UK BS 7671 Wiring Regulations or BS 6396 Office and Educational Systems Best Practice). Incorrect use could lead to risk of electrocution.
- Isolate the supply before installation or repositioning.
- Product to be used only for the intended purpose of managing power and data cables in office and commercial environments.
- Do not overload.

Product care

- Clean using a dry cloth. No abrasives or solvents to be used on the product.
- Do not drop or expose to moisture.

CE UKCA

cmd